



TECH CENTER VIDEOS

THIS IS A CRITICAL ENGINE REPAIR WITH SIGNIFICANT LABOR TIME.
WATCH A SHORT VIDEO FOR INSTRUCTIONS ON YOUR SPECIFIC REPAIR.

SAVE TIME ♦ SAVE MONEY ♦ REDUCE COMEBACKS

THUMBNAIL	VEHICLE PLATFORM	ENGINE	KIT FAMILY	LENGTH	QR CODE
<p>CLOYES 9-0397SA Chrysler 2.7L TIMING CHAIN REPLACEMENT</p>	CHRYSLER DODGE	2.7L	9-0397 9-0707	9:38	
<p>CLOYES 9-0393SF Chrysler 4.7L TIMING CHAIN REPLACEMENT</p>	CHRYSLER DODGE ♦ JEEP RAM	3.7L ♦ 4.7L	9-0393	10:49	
<p>CLOYES 9-0398SB Ford 4.0L TIMING CHAIN REPLACEMENT</p>	FORD MERCURY ♦ MAZDA	4.0L	9-0398	12:00	
<p>CLOYES 9-4226S & 9-0738S Ford 3.5/3.7L DOHC V6 TIMING CHAIN REPLACEMENT</p>	FORD LINCOLN ♦ MAZDA MERCURY	3.3L 3.5L ♦ 3.7L	9-4226 9-0738	10:27	
<p>CLOYES 9-0391SB Ford 5.4L TIMING CHAIN REPLACEMENT</p>	FORD LINCOLN ♦ MERCURY	4.6L 5.4L ♦ 6.8L	9-0387 9-0391	8:50	
<p>CLOYES 9-0391SBVVT Ford 5.4L V8 DIAGNOSING VVT CAM PHASER ISSUES</p>	FORD LINCOLN ♦ MERCURY	4.6L 5.4L ♦ 6.8L	9-0387 9-0391	3:09	
<p>CLOYES 9-4205SA GM Gen 3/4 TIMING CHAIN REPLACEMENT</p>	GM BUICK ♦ CADILLAC CHEVROLET ♦ GMC HUMMER ♦ PONTIAC	4.8L ♦ 5.3L 5.7L ♦ 6.0L 6.2L ♦ 7.0L	C-3210 C-3220 C-3227 C-3229 9-4205	5:58	

THUMBNAIL	VEHICLE PLATFORM	ENGINE	KIT FAMILY	LENGTH	QR CODE
-----------	------------------	--------	------------	--------	---------



GM
 BUICK ♦ CHEVROLET
 GMC ♦ OLDSMOBILE
 PONTIAC ♦ SATURN

2.0L
 2.2L ♦ 2.4L

9-4201
 9-4202

14:31



GM
 BUICK ♦ CADILLAC
 CHEVROLET ♦ GMC
 PONTIAC ♦ SATURN

2.8L
 3.0L ♦ 3.6L

9-0753

7:00



GM
 BUICK ♦ CADILLAC
 CHEVROLET ♦ GMC
 PONTIAC ♦ SATURN

2.8L
 3.0L ♦ 3.6L

9-0753

8:43



HONDA
 ACURA ♦ HONDA

2.4L (K24)

9-0711

8:20



NISSAN
 INFINITI

3.5L ♦ 4.0L

9-0719
 9-0720
 9-0730

10:12



TOYOTA
 LEXUS ♦ SCION

2.0L
 2.5L ♦ 2.7L

9-4313

8:15

